

## ZEP FORMULA 6556<sup>™</sup> Acid Descaler Cleaner

#### DESCRIPTION

Powerful, liquid, muriatic acid based cleaner, formulated to clean cement mixing and handling equipment, etching concrete floors, cleaning masonry surfaces, removing hard water scale, rust, and similar soils quickly.

#### **FEATURES**

Quick penetrating

Corrosion inhibitors

Acceptable for use in food

#### **BENEFITS**

- Contains special wetting agents to provide rapid penetration of surfaces to be cleaned
- · Has corrosion inhibitors to retard attck on base metals
- Acid cleaner for use in all federally inspected meat processing APPLICATIONS and poultry plants.

#### **APPLICATIONS**

Removes portland cement, lime, or concrete from metal equipment, machinery and concrete mixers. Etches concrete floors prior to application of certain floor sealing compounds

Ready Mix Trucks Heating and Cooling Large Kitchen Areas Warehouses **Equipment Repair** 

\* Because muriatic acid emits irritating and corrosive fumes when used, provisions for adequate ventilation must be provided.

#### **COMPANION PRODUCTS**

Zep TNT, Zep-O-Shine, Zep Concrete Cleaning Station 3, Zep XT-3600 (Cleaner, Neutralizer, Wax)

#### **SPECIFICATIONS**

Physical form ......BROWN LIQUID Flash point (TCC) .....None Odor .....STRONG, IRRITATING ACIDIC FUMES pH (concentrate) ......<1 Specific gravity ......1.13

(1% solution)	.1.0-2.0
Boiling point	.212°F
Shelf life	.1 year minimum
DOT Shipping label	.CORROSIVE LIQUID, ACIDIC,
	.INORGANIC, N.O.S.

#### PACKAGING

4 gallon case 8 gallon case 5 gallon pail 20 gallon drum 55 gallon drum

### ZEP MANUFACTURING COMPANY

Your One Source for Cleaning and Maintenance Products

1-877-I BUY ZEP (1-877-428-9937)

PROD.# 1093 890D



# ZEP FORMULA 6556<sup>™</sup> **Acid Descaler Cleaner**



PRECAUCION AL USUARIO: Si usted no lee inglés, no use este producto hasta que la etiqueta le haya sidc explicada ámplamente. (TO THE USER: II you cannot read English, do no use hits product until the label has been fully explained to you.)

product is designed exclusively for industrial and tutional use by trained, professional maintenance onnel Label directions and precautions must be wed exactly. Zep Manufacturing Company will be responsible for any injury, loss, or damage if duct is used in any manner not in compliance with directions, or if orecautions are not observed.

#### HMIS RATINGS

HEALTH	3	4 EXTREME
FLAMMABILITY	0	3 SERIOUS 2 MODERATE
REACTIVITY	1	1 SLIGHT 0 MINIMAL
PERSONAL PROTECTION EQUIPMENT	х	Requres Special Handling

### ZEP FORMULA 6556<sup>™</sup> CHEMICAL CLEANER A CONCENTRATE - MUST BE DILUTED FOR USE

A spricially compounded, inhibited acid cleaner useful in: Removing portland cement, lime or concrete from metal equipment, machinery, cement mixers, transit forms, shovels. Cleaning of concerve macary, graze the, super, concrete blocks. Removing excess mortar from brick with or ceramic tilf. Can br, used to descale air conditioners, water systems, and dishwashers

DIRECTION: MASONRY, STONE, or COACPE (E: Dilute 1, and trade ut with 1 part water and apply with a mop or bursh. Allow 5 minutes contact intwine, and flush off whit water. COMENT, LIME or CONCRETE FRCM. MF.[] LEQUIPMENT: Dilute 1 part with 6 parts water. ply on surface with brush if note (san). Allow 5 minutes contact time and flush with water, average deposits may require a stronger solution or repeated application.

Inside mixers, use a dilution of house of house and allow mixer ing. Buch out with planty of weiter For clearing autore of mixer use for remaining concrete from in-stal equipment. NCREFE MIXE tions stated abov

rt out of the succo, THIS IS VEFLY IN PORTANT ain and flush all w esh water

culate the pipes, suinp and storage tanks. ULA \$556 for each 24 galons of Starti treatment the syste

 Start pump and operate sys maintain a pH of 2 to 3 during. . ORMULA ling add 6556 if necessary as acid is neutri 5. In the case of air conditioners a In the case of air conditioners and indu head pressure indicates progress in the rer ctorec n scale

head pressure indicates progress in the removal of system scale. In 6. When scale and deposits have been satisfactory, removed and dispose in suitable way and refill with fresh water, circonte for 19 system again. 7. Refill system with water and restore normal operation of mach system as soon as practical after cleaning. ery,

NOTE: Fumes from acid solutions may cause rusting of sensitive metal surfaces steel). Such surfaces should be removed from area of application or otherwise prof fumes. DO NOT USE ON ALUMINUM. n &

Care should be taken to avoid contact with painted surfaces since many paints are noitive

Authorized by USDA for use in federally-inspected meat and poultry plants.

DANGER! Contains hydrochloric acid. CAUSES BURNS (index) Ŵ HARMFUL OR FATAL IF SWALLOWED **POISON!** 

CONTACT CAN CAUSE SEVERE SKIN BURNS AND BUNDNESS BY TISSUE CORROSION, DO CONTACT CAN CAUSE SEVENE SINT BURNS AND BUINDIESS BY TISSUE CONHOSION. DO NOT allow product to contact skin, eyes, or clothing. DO NOT swallow this product. DO NOT breather vapors or spray mist. Inhalation of vapors or spray mist can cause respiratior tract irritation. Repeated exposure can have cumulative effects. Exposure may aggravate existing respiratory, heart, skin, or eye disorders. Further information on the effects of voreexposure is included on the Material Safety Data Sheet, which is available upon request.

Material Safety Data Sheet, which is available upon request. Zep advocates limiting exposure to all chemical products. Wear tight-fitting, splash-proof safety goggles during product use and when eye contact is possible. DO NOT wear contact lenses during product use. Wear nitrile, neoprene, naturall rubber, or other resistant gloves and acid resistant footwear also wear a face shield and rubber apron whenever splashing can occur. Use product in well-ventilated areas only; open windows/doors and use exhaust fans in enclosed areas. Remove contaminated clothing promytly and DO NOT rewear until thoroughly cleaned. After handling, wash hands thoroughly with soap and water.

#### FIRST AID:

ETRS: imm-diately flush eyes with plenty of water for at least 15 minutes, occasionally lifting the upper and Jower eyelids. Get medical attention immediately. SKI:: Irm reliately flush contaminated skin with plenty of water for at least 15 minutes. Get medical attention immediately. INAL/LTION: Move expose\_percont or fresh air at once. If breathing has stopped, perform rtificial respiration. Get m-dical attention immediately.

**INGESTION:** If this product is availe wed, DO NOT induce vomiting. If affected person is conscious give penty of water to drink. Get medical attention at once.

DISPOSAL \*/V/OR SPILL INFORMATI/N: As with all chaning and maintenance procedures, run-off from the chaning or main enance process shruld be divarted to a collection vessel, or where pervitted, to a sanitary sew er (crynsul, iconal and state regulations) and not allowed to soak into the gloon or to enter a trom sev.er. If this pruduc, is spilled or contaminates and cannot be used, opating the need for disposal, absolb product on in inert absorbent material, such as Zep-O-Zortf or Zep Super Sorbent, and departs in a chan, readable D.O.T. specification contuiner for disposal as a hazardous waste. Brine area vell with water.

